


CM

MEASUREMENT CONVERTER

DIMENSIONS



JUNCTIONS

TERMINAL	DESCRIPTION	
1	Aux. Supply Voltage	115 ou 230Vac / 50Hz
2	Aux. Supply Voltage	115 ou 230Vac / 50Hz
3	N.A.	
4	Input I-	
5	Input I+	
6	Output O+	
7	Output O-	
8	N.A.	
9	N.A.	
10	N.A.	