

## VMRA

## MILLIVOLTMETER

### Anode voltage distribution measurement VMRA

Assemble and connect with a cane CMRA.C type or connect with a cane CMRA type.

Press the two tips of the measurement cane against the anode assembly stem below the anode beam. The tips must be vertically aligned, parallel with the anode assembly.

Read the measured voltage on the digital display.

### Measurement of the stem-anode beam contact CCTC

Connect a sliding tip cane CCTC type.

Press on tip onto the anode beam and the other on the anode assembly stem, along the same horizontal plane below the connector.

Read the measured voltage on the digital display.